

## PRELIMINARY SUMMARY OF MAP ACTIONS

Community: LA PORTE COUNTY

Community No: 180144

To assist your community in maintaining the Flood Insurance Rate Map (FIRM), we have summarized below the previously issued Letter of Map Change (LOMC) actions (i.e., Letters of Map Revision (LOMRs) and Letters of Map Amendment (LOMAs)) that will be affected by the preparation of the enclosed revised FIRM panel(s).

**1. LOMCs Incorporated**

The modifications effected by the LOMCs listed below have been reflected on the Preliminary copies of the revised FIRM panels. In addition, these LOMCs will remain in effect until the revised FIRM becomes effective.

LOMC	Case No.	Date Issued	Project Identifier	Old Panel	New Panel
			NO CASES RECORDED		

**2. LOMCs Not Incorporated**

The modifications effected by the LOMCs listed below have not been reflected on the Preliminary copies of the revised FIRM panels because of scale limitations or because the LOMC issued had determined that the lot(s) or structure(s) involved were outside the Special Flood Hazard Area, as shown on the FIRM. These LOMCs will be revalidated free of charge 1 day after the revised FIRM becomes effective through a single revalidation letter that reaffirms the validity of the previous LOMCs.

LOMC	Case No.	Date Issued	Project Identifier	Old Panel	New Panel
LOMA	199101419FIA	05/25/1988			18091C0470D
LOMA	98-05-1726A	01/21/1998	10252 W. 2400 SOUTH - SECTION 5	1801440250C	18091C0470D
LOMA	99-05-596A	01/13/1999	TREE HAVEN SUBDIVISION, NORTH SHORE ADDITION - LOT 5 - 5 ELM PLACE	1801440125C	18091C0163D
LOMA	99-05-4158A	10/13/1999	OAK POINT ADDITION - LOT 6 - 408 OAK DRIVE	1801440125C	18091C0163D
LOMA	00-05-2192A	07/25/2000	15 ELM DRIVE	1801440125C	18091C0163D
LOMA	02-05-2147A	10/18/2002	SW1/4 OF SECTION 23, TOWNSHIP 33 NORTH, RANGE 4 WEST; 21886 SOUTH 800 WEST	1801440250C	18091C0500D
LOMA	03-05-3470A	06/04/2003	A PORTION OF SECTION 33, T38N, R3W; 6410 NORTH 300 WEST	1801440050C	18091C0135D
LOMA	04-05-0705A	11/21/2003	7256 W 2200 S	1801440250C	18091C0500D

## PRELIMINARY SUMMARY OF MAP ACTIONS

Community: LA PORTE COUNTY

Community No: 180144

LOMC	Case No.	Date Issued	Project Identifier	Old Panel	New Panel
LOMA	04-05-2243A	03/19/2004	SECTION 35, T34N, R3W; 17325 S. STATE ROAD 39	1801440275C	18091C0505D
LOMA	05-05-0152A	12/08/2004	2777 WEST 1650 SOUTH -- PORTION OF SECTION 27, T34N, R3W	1801440200C	18091C0500D
LOMA	05-05-3550A	11/10/2005	3532 SOUTH 800 EAST -- PORTION OF SECTION 20, T36N, R1W	1801440150C	18091C0325D
LOMR	06-05-B876P	06/29/2006	Earl Road Flood Control Facility	1801440025C	18091C0116D
LOMA	07-05-1554A	03/22/2007	OAK BEACH SUMMER COLONY, PORTION OF LOT 11 -- 3588 SOUTH 800 EAST (IN)	1801440150C	18091C0325D
LOMA	08-05-3894A	07/15/2008	PORTION OF SECTION 34, T33N, R4W -- 8748 WEST 2300 SOUTH	1801440250C	18091C0470D
LOMA	08-05-5162A	10/07/2008	OAK BEACH SUMMER COLONY, LOT 16 -- 3544 SOUTH 800 EAST	1801440150C	18091C0325D
LOMA	08-05-4940A	11/13/2008	PORTION OF SECTION 18, T38N, R3W -- 5334 WEST COUNTY ROAD 1000 NORTH	1801440025C	18091C0043D
LOMA	09-05-0076A	11/28/2008	340 GRAYSON ROAD -- LOT M, RESUBDIVISION OF LOT 10, HOLMES ISLAND SUBDIVISION	1801440125C	18091C0145D
LOMA	09-05-1181A	02/03/2009	PORTION OF LOTS 1-2, HILLCREST ADDITION TO TREE HAVEN SUBDIVISION -- 364 OAK DRIVE	1801440125C	18091C0163D
LOMA	09-05-1527A	03/03/2009	6526 EAST STATE ROAD 4 -- PORTION OF SECTION 18, T36N, R1W	1801440150C	18091C0325D
LOMA	09-05-1576A	03/03/2009	6556 EAST STATE ROAD 4 -- PORTION OF SECTION 18, T36N, R1W	1801440150C	18091C0325D
LOMA	09-05-2402A	06/18/2009	PORTION OF SECTION 18, T36N, R1W -- 6402 EAST STATE ROAD 4	1801440150C	18091C0325D

## 3. LOMCs Superseded

The modifications effected by the LOMCs listed below have not been reflected on the Preliminary copies of the revised FIRM panels because they are being superseded by new detailed flood hazard information or the information available was not sufficient to make a determination. The reason each is being superseded is noted below. These LOMCs will no longer be in effect when the revised FIRM becomes effective.

LOMC	Case No.	Date Issued	Project Identifier	Reason Determination Will be Superseded
			NO CASES RECORDED	

**PRELIMINARY SUMMARY OF MAP ACTIONS**

Community: LA PORTE COUNTY

Community No: 180144

1. Insufficient information available to make a determination.
2. Lowest Adjacent Grade and Lowest Finished Floor are below the proposed Base Flood Elevation.
3. Lowest Ground Elevation is below the proposed Base Flood Elevation.
4. Revised hydrologic and hydraulic analyses.
5. Revised topographic information.

**4. LOMCs To Be Redetermined**

The LOMCs in Category 2 above will be revalidated through a single revalidation letter that reaffirms the validity of the determination in the previously issued LOMC. For LOMCs issued for multiple lots or structures where the determination for one or more of the lots or structures has changed, the LOMC cannot be revalidated through this administrative process. Therefore, we will review the data previously submitted for the LOMC requests listed below and issue a new determination for the affected properties after the effective date of the revised FIRM.

LOMC	Case No.	Date Issued	Project Identifier	Old Panel	New Panel
			NO CASES RECORDED		